

Project Image



Project Information

Client Name	CLIENT
Organization Name	BIM GUIDE HUB
Organization Description	Architecture
Project Number	
Project Name	
Project Address	
Building Name	
Model Author	BO
Project Issue Date	
Project Status	TENDER
Software Version	AUTODESK REVIT 2023

Coordinates

Project Base Point Coordinate	Project Base Point Elevation	Project Base Point Rotation	Survey Point Coordinate	Survey Point Elevation
542565640 E/W 260443156 N/S	23163	342	542565640 E/W 260443156 N/S	23163

Overall Result




Elements

12869

Placed Elements

423

Total Family




Placed Right Workset

2050

Placed Wrong Workset

10334




Family/Type Right Named

5

Family/Type Wrong Named

418




Type Marked

241

No Type Mark

182




Keynoted

47

No Keynote

376




Marked

3941

No Marked

8928




Description

136

No Description

287




Assembly Coded

0

No Assembly Code

423




Manufacturer

24

No Manufacturer

399


Model Elements



Architectural Elements

10225
Architectural Elements

377
Arc. Total Family




Placed Right Workset

500

Placed Wrong Workset

9240




Family/Type Right Named

5

Family/Type Wrong Named

372




Type Marked

238

No Type Mark

139




Keynoted

43

No Keynote

334




Marked

1492

No Marked

8733




Description

128

No Description

249




Assembly Coded

0

No Assembly Code

377



Manufacturer

16


No Manufacturer

361

Casework

1592
Placed

55
Total Family




Placed Right Workset

0

Placed Wrong Workset

1592




Family/Type Right Named

0

Family/Type Wrong Named

55



Type Marked

2

No Type Mark

53



Keynoted

0

No Keynote

55




Marked

0

No Mark

1592



Description

3

No Description

52




Assembly Coded

0

No Assembly Coded

55




Manufacturer

5


No Manufacturer

50


Ceiling




Placed Right Workset
0
Placed Wrong Workset
192




Family/Type Right Named
0
Family/Type Wrong Named
4




Type Marked
3
No Type Mark
1




Keynoted
0
No Keynote
4




Marked
0
No Mark
192



Description
3
No Description
1





Assembly Coded
0
No Assembly Coded
4




Manufacturer
0
No Manufacturer
4


Column (Architectural)



Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
(Blank)
No Manufacturer
(Blank)


Curtain Mullion




Placed Right Workset
(Blank)
Placed Wrong Workset
(Blank)



Family/Type Right Named
0
Family/Type Wrong Named
7




Type Marked
1
No Type Mark
6




Keynoted
0
No Keynote
7




Marked
0
No Mark
328



Description
0
No Description
7





Assembly Coded
0
No Assembly Coded
7




Manufacturer
0
No Manufacturer
7


Curtain Panel



Placed Right Workset
(Blank)
Placed Wrong Workset
(Blank)




Family/Type Right Named
2
Family/Type Wrong Named
17




Type Marked
9
No Type Mark
10




Keynoted
0
No Keynote
19




Marked
0
No Mark
157



Description
0
No Description
19





Assembly Coded
0
No Assembly Coded
19




Manufacturer
0
No Manufacturer
19


Exterior Door




Placed Right Workset
50
Placed Wrong Workset
10




Family/Type Right Named
0
Family/Type Wrong Named
5



Type Marked
4
No Type Mark
1




Keynoted
0
No Keynote
5




Marked
57
No Mark
3



Description
0
No Description
5




Assembly Coded
0
No Assembly Coded
5




Manufacturer
0
No Manufacturer
5


Interior Door




Placed Right Workset
0
Placed Wrong Workset
559




Family/Type Right Named
0
Family/Type Wrong Named
33




Type Marked
28
No Type Mark
5



Keynoted
3
No Keynote
30




Marked
547
No Mark
12



Description
14
No Description
19





Assembly Coded
0
No Assembly Coded
33




Manufacturer
3
No Manufacturer
30


Floor (Finishes)




Placed Right Workset
0
Placed Wrong Workset
258




Family/Type Right Named
0
Family/Type Wrong Named
13




Type Marked
12
No Type Mark
1




Keynoted
0
No Keynote
13




Marked
0
No Mark
258



Description
10
No Description
3





Assembly Coded
0
No Assembly Coded
13




Manufacturer
0
No Manufacturer
13


Furniture




Placed Right Workset
0
Placed Wrong Workset
658




Family/Type Right Named
0
Family/Type Wrong Named
24




Type Marked
11
No Type Mark
13




Keynoted
0
No Keynote
24




Marked
0
No Mark
658



Description
11
No Description
13





Assembly Coded
0
No Assembly Coded
24




Manufacturer
0
No Manufacturer
24


Generic Model




Placed Right Workset
0
Placed Wrong Workset
1659




Family/Type Right Named
3
Family/Type Wrong Named
74




Type Marked
66
No Type Mark
11



Keynoted
0
No Keynote
77




Marked
5
No Mark
1654



Description
7
No Description
70




Assembly Coded
0
No Assembly Coded
77




Manufacturer
2
No Manufacturer
75


Railing




Placed Right Workset
50
Placed Wrong Workset
33




Family/Type Right Named
0
Family/Type Wrong Named
4



Type Marked
0
No Type Mark
4




Keynoted
0
No Keynote
4




Marked
50
No Mark
33



Description
0
No Description
4





Assembly Coded
0
No Assembly Coded
4




Manufacturer
0
No Manufacturer
4


Ramp (Finishes)




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1



Manufacturer
0
No Manufacturer
1


Roof



Placed Right Workset
50
Placed Wrong Workset
7




Family/Type Right Named
0
Family/Type Wrong Named
4




Type Marked
0
No Type Mark
4




Keynoted
0
No Keynote
4




Marked
50
No Mark
7



Description
0
No Description
4





Assembly Coded
0
No Assembly Coded
4




Manufacturer
0
No Manufacturer
4


Site




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Stair (Finishes)




Placed Right Workset
50
Placed Wrong Workset
10




Family/Type Right Named
0
Family/Type Wrong Named
2




Type Marked
0
No Type Mark
2




Keynoted
1
No Keynote
1




Marked
50
No Mark
10



Description
0
No Description
2





Assembly Coded
0
No Assembly Coded
2




Manufacturer
0
No Manufacturer
2


Wall (Curtain)




Placed Right Workset
50
Placed Wrong Workset
34




Family/Type Right Named
0
Family/Type Wrong Named
9




Type Marked
7
No Type Mark
2




Keynoted
2
No Keynote
7




Marked
61
No Mark
23



Description
1
No Description
8





Assembly Coded
0
No Assembly Coded
9




Manufacturer
0
No Manufacturer
9


Wall (Interior)




Placed Right Workset
0
Placed Wrong Workset
3587




Family/Type Right Named
0
Family/Type Wrong Named
47




Type Marked
37
No Type Mark
10




Keynoted
22
No Keynote
25




Marked
34
No Mark
3553



Description
25
No Description
22





Assembly Coded
0
No Assembly Coded
47




Manufacturer
2
No Manufacturer
45


Wall (Exterior)




Placed Right Workset
0
Placed Wrong Workset
415




Family/Type Right Named
0
Family/Type Wrong Named
30




Type Marked
20
No Type Mark
10




Keynoted
15
No Keynote
15



Marked
174
No Mark
241



Description
16
No Description
14




Assembly Coded
0
No Assembly Coded
30



Manufacturer
3
No Manufacturer
27

Wall (Retaining)




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Wall (Soffit)



Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Window




Placed Right Workset
0
Placed Wrong Workset
221




Family/Type Right Named
0
Family/Type Wrong Named
39




Type Marked
38
No Type Mark
1




Keynoted
0
No Keynote
39




Marked
214
No Mark
7



Description
38
No Description
1



Assembly Coded
0
No Assembly Coded
39



Manufacturer
0
No Manufacturer
39


MEP Elements

2097

Architectural Elements

34

Arc. Total Family




Placed Right Workset

1100

Placed Wrong Workset

997




Family/Type Right Named

0

Family/Type Wrong Named

34




Type Marked

1

No Type Mark

33




Keynoted

2

No Keynote

32




Marked

1999

No Marked

98




Description

8

No Description

26




Assembly Coded

0

No Assembly Code

34



Manufacturer

8

No Manufacturer

26


Air Terminal

51

Placed

1

Total Family



Placed Right Workset

50

Placed Wrong Workset

1



Family/Type Right Named

0

Family/Type Wrong Named

1




Type Marked

0

No Type Mark

1



Keynoted

0

No Keynote

1



Marked

51

No Mark

0



Description

0

No Description

1




Assembly Coded

0

No Assembly Coded

1





Manufacturer

0

No Manufacturer

1


Cable Tray




Placed Right Workset
50
Placed Wrong Workset
3




Family/Type Right Named
0
Family/Type Wrong Named
2




Type Marked
0
No Type Mark
2




Keynoted
0
No Keynote
2




Marked
50
No Mark
3



Description
0
No Description
2





Assembly Coded
0
No Assembly Coded
2




Manufacturer
0
No Manufacturer
2


Conduit




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Communication Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Data Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Fire Alarm Device



Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1



Manufacturer
0
No Manufacturer
1


Lighting Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Nurse Call Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Telephone Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Security Device




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Duct



Placed Right Workset
50
Placed Wrong Workset
3




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
3



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Electrical Equipment




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Electrical Fixture




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Flex Duct




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Flex Pipe




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Lighting Fixture




Placed Right Workset
50
Placed Wrong Workset
1



Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
51
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Mechanical Equipment




Placed Right Workset
0
Placed Wrong Workset
186



Family/Type Right Named
0
Family/Type Wrong Named
4




Type Marked
0
No Type Mark
4




Keynoted
1
No Keynote
3




Marked
186
No Mark
0



Description
1
No Description
3





Assembly Coded
0
No Assembly Coded
4




Manufacturer
1
No Manufacturer
3


Pipe




Placed Right Workset
50
Placed Wrong Workset
3




Family/Type Right Named
0
Family/Type Wrong Named
2



Type Marked
0
No Type Mark
2




Keynoted
0
No Keynote
2




Marked
50
No Mark
3



Description
0
No Description
2





Assembly Coded
0
No Assembly Coded
2



Manufacturer
0
No Manufacturer
2


Plumbing Fixture




Placed Right Workset
0
Placed Wrong Workset
708




Family/Type Right Named
0
Family/Type Wrong Named
8




Type Marked
1
No Type Mark
7




Keynoted
1
No Keynote
7




Marked
700
No Mark
8



Description
7
No Description
1




Assembly Coded
0
No Assembly Coded
8




Manufacturer
7
No Manufacturer
1


Speciality Equipment




Placed Right Workset
0
Placed Wrong Workset
78




Family/Type Right Named
0
Family/Type Wrong Named
2




Type Marked
0
No Type Mark
2




Keynoted
0
No Keynote
2




Marked
0
No Mark
78



Description
0
No Description
2




Assembly Coded
0
No Assembly Coded
2




Manufacturer
0
No Manufacturer
2


Sprinkler



Placed Right Workset
50
Placed Wrong Workset
2



Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
52
No Mark
0



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1



Manufacturer
0
No Manufacturer
1

Structural Elements




Placed Right Workset

600

Placed Wrong Workset

367




Family/Type Right Named

0

Family/Type Wrong Named

29




Type Marked

14

No Type Mark

15




Keynoted

3

No Keynote

26




Marked

600

No Marked

367




Description

10

No Description

19




Assembly Coded

0

No Assembly Code

29




Manufacturer

0

No Manufacturer

29

Floor (Structural)




Placed Right Workset

0

Placed Wrong Workset

258




Family/Type Right Named

0

Family/Type Wrong Named

13




Type Marked

12

No Type Mark

1



Keynoted

0

No Keynote

13




Marked

0

No Mark

258




Description

10

No Description

3




Assembly Coded

0

No Assembly Coded

13





Manufacturer

0


No Manufacturer

13


Ramp (Structural)



Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Rebar




Placed Right Workset
50
Placed Wrong Workset
3




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
3



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Stair (Structural)




Placed Right Workset
50
Placed Wrong Workset
10




Family/Type Right Named
0
Family/Type Wrong Named
2




Type Marked
0
No Type Mark
2




Keynoted
1
No Keynote
1




Marked
50
No Mark
10



Description
0
No Description
2




Assembly Coded
0
No Assembly Coded
2




Manufacturer
0
No Manufacturer
2


Structural Column




Placed Right Workset
0
Placed Wrong Workset
76




Family/Type Right Named
0
Family/Type Wrong Named
5




Type Marked
2
No Type Mark
3




Keynoted
2
No Keynote
3




Marked
0
No Mark
76



Description
0
No Description
5





Assembly Coded
0
No Assembly Coded
5




Manufacturer
0
No Manufacturer
5


Structural Foundation




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1



Manufacturer
0
No Manufacturer
1

Structural Framing




Placed Right Workset
50
Placed Wrong Workset
13




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
13



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Structural Stiffener




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Structural Truss




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1




Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Wall (Foundation)




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1



Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1





Assembly Coded
0
No Assembly Coded
1




Manufacturer
0
No Manufacturer
1


Wall (Core-Shaft)




Placed Right Workset
50
Placed Wrong Workset
1




Family/Type Right Named
0
Family/Type Wrong Named
1




Type Marked
0
No Type Mark
1




Keynoted
0
No Keynote
1




Marked
50
No Mark
1



Description
0
No Description
1



Assembly Coded
0
No Assembly Coded
1



Manufacturer
0
No Manufacturer
1

