

Project Image



Project Information

Client Name	CLIENT
Organization Name	BIM GUIDE HUB
Organization Description	Architect
Project Number	
Project Name	
Project Address	
Building Name	Residential Building
Model Author	BO
Project Issue Date	
Project Status	
Software Version	AUTODESK REVIT 2021.1.7




Coordinates

Project Base Point Coordinate	Project Base Point Elevation	Project Base Point Rotation	Survey Point Coordinate	Survey Point Elevation
389236542 E/W 390229108 N/S	51650	325.02°	389000000 E/W 390000000 N/S	0

Overall Result



Elements




EF Number Yes Value

176

EF Number No Value

209




EF Description Yes Value

251

EF Description No Value

134




Ss Number Yes Value

254

Ss Number No Value

131




Ss Description Yes Value

256

Ss Description No Value

129




Pr Number Yes Value

200

Pr Number No Value

185




Pr Description Yes Value

200

Pr Description No Value

185

Element Types



Architectural Elements

29166


Architectural Elements

Architectural Overall Result



306

Arc. Total Family




EF Number Yes Value

155

EF Number No Value

151




EF Description Yes Value

229

EF Description No Value

77




Ss Number Yes Value

231

Ss Number No Value

75




Ss Description Yes Value

233

Ss Description No Value

73




Pr Number Yes Value

168

Pr Number No Value

138



Pr Description Yes Value

168

Pr Description No Value

138


Casework

0

Placed

0

Total Family




EF Number Yes Value

0

EF Number No Value

0




EF Description Yes Value

0

EF Description No Value

0




Ss Number Yes Value

0

Ss Number No Value

0




Ss Description Yes Value

0

Ss Description No Value

0



Pr Number Yes Value

0

Pr Number No Value

0




Pr Description Yes Value

0


Pr Description No Value

0


Ceiling




EF Number Yes Value
3
EF Number No Value
5




EF Description Yes Value
4
EF Description No Value
4



Ss Number Yes Value
6
Ss Number No Value
2



Ss Description Yes Value
7
Ss Description No Value
1





Pr Number Yes Value
4
Pr Number No Value
4



Pr Description Yes Value
4
Pr Description No Value
4


Column (Architectural)




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0



Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0

Curtain Mullion



EF Number Yes Value
8
EF Number No Value
0



EF Description Yes Value
8
EF Description No Value
0



Ss Number Yes Value
8
Ss Number No Value
0



Ss Description Yes Value
8
Ss Description No Value
0




Pr Number Yes Value
8
Pr Number No Value
0




Pr Description Yes Value
8
Pr Description No Value
0


Curtain Panel




EF Number Yes Value
7
EF Number No Value
1




EF Description Yes Value
7
EF Description No Value
1




Ss Number Yes Value
7
Ss Number No Value
1



Ss Description Yes Value
7
Ss Description No Value
1




Pr Number Yes Value
7
Pr Number No Value
1



Pr Description Yes Value
7
Pr Description No Value
1

Exterior Door



EF Number Yes Value
17
EF Number No Value
0



EF Description Yes Value
17
EF Description No Value
0



Ss Number Yes Value
17
Ss Number No Value
0



Ss Description Yes Value
17
Ss Description No Value
0




Pr Number Yes Value
17
Pr Number No Value
0




Pr Description Yes Value
17
Pr Description No Value
0


Interior Door




EF Number Yes Value
33
EF Number No Value
3




EF Description Yes Value
33
EF Description No Value
3




Ss Number Yes Value
33
Ss Number No Value
3



Ss Description Yes Value
33
Ss Description No Value
3





Pr Number Yes Value
33
Pr Number No Value
3




Pr Description Yes Value
33
Pr Description No Value
3


Floor (Finishes)




EF Number Yes Value
21
EF Number No Value
1




EF Description Yes Value
21
EF Description No Value
1




Ss Number Yes Value
21
Ss Number No Value
1



Ss Description Yes Value
21
Ss Description No Value
1





Pr Number Yes Value
21
Pr Number No Value
1




Pr Description Yes Value
21
Pr Description No Value
1


Furniture




EF Number Yes Value
11
EF Number No Value
1




EF Description Yes Value
11
EF Description No Value
1




Ss Number Yes Value
11
Ss Number No Value
1



Ss Description Yes Value
11
Ss Description No Value
1




Pr Number Yes Value
11
Pr Number No Value
1




Pr Description Yes Value
11
Pr Description No Value
1


Generic Model




EF Number Yes Value
0
EF Number No Value
61




EF Description Yes Value
32
EF Description No Value
29




Ss Number Yes Value
32
Ss Number No Value
29



Ss Description Yes Value
32
Ss Description No Value
29




Pr Number Yes Value
0
Pr Number No Value
61




Pr Description Yes Value
0
Pr Description No Value
61


Railing




EF Number Yes Value
9
EF Number No Value
3




EF Description Yes Value
9
EF Description No Value
3




Ss Number Yes Value
9
Ss Number No Value
3



Ss Description Yes Value
9
Ss Description No Value
3




Pr Number Yes Value
9
Pr Number No Value
3



Pr Description Yes Value
9
Pr Description No Value
3

Ramp (Finishes)



EF Number Yes Value
1
EF Number No Value
0



EF Description Yes Value
1
EF Description No Value
0



Ss Number Yes Value
1
Ss Number No Value
0



Ss Description Yes Value
1
Ss Description No Value
0




Pr Number Yes Value
1
Pr Number No Value
0




Pr Description Yes Value
1
Pr Description No Value
0


Roof




EF Number Yes Value
4
EF Number No Value
7




EF Description Yes Value
4
EF Description No Value
7




Ss Number Yes Value
4
Ss Number No Value
7



Ss Description Yes Value
4
Ss Description No Value
7




Pr Number Yes Value
4
Pr Number No Value
7




Pr Description Yes Value
4
Pr Description No Value
7


Site




EF Number Yes Value
0
EF Number No Value
1




EF Description Yes Value
0
EF Description No Value
1




Ss Number Yes Value
0
Ss Number No Value
1



Ss Description Yes Value
0
Ss Description No Value
1





Pr Number Yes Value
0
Pr Number No Value
1




Pr Description Yes Value
0
Pr Description No Value
1


Stair (Finishes)




EF Number Yes Value
2
EF Number No Value
1




EF Description Yes Value
2
EF Description No Value
1




Ss Number Yes Value
2
Ss Number No Value
1



Ss Description Yes Value
2
Ss Description No Value
1




Pr Number Yes Value
2
Pr Number No Value
1



Pr Description Yes Value
2
Pr Description No Value
1

Wall (Curtain)



EF Number Yes Value
3
EF Number No Value
0



EF Description Yes Value
3
EF Description No Value
0



Ss Number Yes Value
3
Ss Number No Value
0



Ss Description Yes Value
3
Ss Description No Value
0




Pr Number Yes Value
3
Pr Number No Value
0




Pr Description Yes Value
3
Pr Description No Value
0


Wall (Interior)




EF Number Yes Value
4
EF Number No Value
47




EF Description Yes Value
28
EF Description No Value
23




Ss Number Yes Value
28
Ss Number No Value
23



Ss Description Yes Value
29
Ss Description No Value
22




Pr Number Yes Value
5
Pr Number No Value
46



Pr Description Yes Value
5
Pr Description No Value
46

Wall (Exterior)



EF Number Yes Value
5
EF Number No Value
17




EF Description Yes Value
22
EF Description No Value
0




Ss Number Yes Value
22
Ss Number No Value
0



Ss Description Yes Value
22
Ss Description No Value
0





Pr Number Yes Value
16
Pr Number No Value
6




Pr Description Yes Value
16
Pr Description No Value
6


Wall (Retaining)




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0




Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Wall (Soffit)




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Window




EF Number Yes Value
27
EF Number No Value
3



EF Description Yes Value
27
EF Description No Value
3




Ss Number Yes Value
27
Ss Number No Value
3



Ss Description Yes Value
27
Ss Description No Value
3



Pr Number Yes Value
27
Pr Number No Value
3



Pr Description Yes Value
27
Pr Description No Value
3


MEP Elements

1419

MEP Elements

65

MEP Total Family




EF Number Yes Value

14

EF Number No Value

51




EF Description Yes Value

15

EF Description No Value

50




Ss Number Yes Value

18

Ss Number No Value

47




Ss Description Yes Value

18

Ss Description No Value

47




Pr Number Yes Value

23

Pr Number No Value

42



Pr Description Yes Value

23

Pr Description No Value

42


Air Terminal

22

Placed

7

Total Family




EF Number Yes Value

5

EF Number No Value

2




EF Description Yes Value

5

EF Description No Value

2




Ss Number Yes Value

5

Ss Number No Value

2




Ss Description Yes Value

5

Ss Description No Value

2




Pr Number Yes Value

5

Pr Number No Value

2




Pr Description Yes Value

5


Pr Description No Value

2


Cable Tray




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Conduit




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Communication Device




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0




Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Data Device




EF Number Yes Value
0
EF Number No Value
3



EF Description Yes Value
0
EF Description No Value
3



Ss Number Yes Value
0
Ss Number No Value
3



Ss Description Yes Value
0
Ss Description No Value
3




Pr Number Yes Value
3
Pr Number No Value
0



Pr Description Yes Value
3
Pr Description No Value
0


Fire Alarm Device




EF Number Yes Value
0
EF Number No Value
3



EF Description Yes Value
0
EF Description No Value
3




Ss Number Yes Value
0
Ss Number No Value
3



Ss Description Yes Value
0
Ss Description No Value
3




Pr Number Yes Value
0
Pr Number No Value
3




Pr Description Yes Value
0
Pr Description No Value
3


Lighting Device



EF Number Yes Value
0
EF Number No Value
4




EF Description Yes Value
0
EF Description No Value
4




Ss Number Yes Value
0
Ss Number No Value
4



Ss Description Yes Value
0
Ss Description No Value
4




Pr Number Yes Value
0
Pr Number No Value
4




Pr Description Yes Value
0
Pr Description No Value
4


Nurse Call Device




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Telephone Device




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Security Device



EF Number Yes Value
0
EF Number No Value
4




EF Description Yes Value
0
EF Description No Value
4




Ss Number Yes Value
0
Ss Number No Value
4



Ss Description Yes Value
0
Ss Description No Value
4




Pr Number Yes Value
1
Pr Number No Value
3




Pr Description Yes Value
1
Pr Description No Value
3


Duct




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Electrical Equipment




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Electrical Fixture




EF Number Yes Value
0
EF Number No Value
4




EF Description Yes Value
0
EF Description No Value
4




Ss Number Yes Value
0
Ss Number No Value
4



Ss Description Yes Value
0
Ss Description No Value
4




Pr Number Yes Value
0
Pr Number No Value
4




Pr Description Yes Value
0
Pr Description No Value
4


Flex Duct




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Flex Pipe




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Lighting Fixture




EF Number Yes Value
1
EF Number No Value
12




EF Description Yes Value
1
EF Description No Value
12




Ss Number Yes Value
1
Ss Number No Value
12



Ss Description Yes Value
1
Ss Description No Value
12




Pr Number Yes Value
1
Pr Number No Value
12




Pr Description Yes Value
1
Pr Description No Value
12


Mechanical Equipment




EF Number Yes Value
3
EF Number No Value
3




EF Description Yes Value
3
EF Description No Value
3



Ss Number Yes Value
3
Ss Number No Value
3



Ss Description Yes Value
3
Ss Description No Value
3




Pr Number Yes Value
3
Pr Number No Value
3



Pr Description Yes Value
3
Pr Description No Value
3


Pipe




EF Number Yes Value
1
EF Number No Value
7



EF Description Yes Value
1
EF Description No Value
7




Ss Number Yes Value
1
Ss Number No Value
7



Ss Description Yes Value
1
Ss Description No Value
7





Pr Number Yes Value
1
Pr Number No Value
7




Pr Description Yes Value
1
Pr Description No Value
7


Plumbing Fixture




EF Number Yes Value
1
EF Number No Value
3




EF Description Yes Value
1
EF Description No Value
3




Ss Number Yes Value
1
Ss Number No Value
3



Ss Description Yes Value
1
Ss Description No Value
3




Pr Number Yes Value
1
Pr Number No Value
3




Pr Description Yes Value
1
Pr Description No Value
3


Speciality Equipment




EF Number Yes Value
3
EF Number No Value
5



EF Description Yes Value
4
EF Description No Value
4



Ss Number Yes Value
7
Ss Number No Value
1



Ss Description Yes Value
7
Ss Description No Value
1





Pr Number Yes Value
8
Pr Number No Value
0



Pr Description Yes Value
8
Pr Description No Value
0


Sprinkler




EF Number Yes Value
0
EF Number No Value
1



EF Description Yes Value
0
EF Description No Value
1




Ss Number Yes Value
0
Ss Number No Value
1



Ss Description Yes Value
0
Ss Description No Value
1



Pr Number Yes Value
0
Pr Number No Value
1



Pr Description Yes Value
0
Pr Description No Value
1

Structural Elements

1465


Structural Elements

Structural Overall Result



41

Str. Total Family




EF Number Yes Value

31

EF Number No Value

10




EF Description Yes Value

31

EF Description No Value

10




Ss Number Yes Value

29

Ss Number No Value

12




Ss Description Yes Value

29

Ss Description No Value

12




Pr Number Yes Value

33

Pr Number No Value

8



Pr Description Yes Value

33

Pr Description No Value

8


Floor (Structural)

1045

Placed

22

Total Family




EF Number Yes Value

21

EF Number No Value

1




EF Description Yes Value

21

EF Description No Value

1




Ss Number Yes Value

21

Ss Number No Value

1




Ss Description Yes Value

21

Ss Description No Value

1




Pr Number Yes Value

21

Pr Number No Value

1



Pr Description Yes Value

21

Pr Description No Value

1

Ramp (Structural)



EF Number Yes Value
1
EF Number No Value
0



EF Description Yes Value
1
EF Description No Value
0



Ss Number Yes Value
1
Ss Number No Value
0



Ss Description Yes Value
1
Ss Description No Value
0





Pr Number Yes Value
1
Pr Number No Value
0



Pr Description Yes Value
1
Pr Description No Value
0


Rebar




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Stair (Structural)




EF Number Yes Value
2
EF Number No Value
1




EF Description Yes Value
2
EF Description No Value
1




Ss Number Yes Value
2
Ss Number No Value
1



Ss Description Yes Value
2
Ss Description No Value
1




Pr Number Yes Value
2
Pr Number No Value
1



Pr Description Yes Value
2
Pr Description No Value
1


Structural Column



EF Number Yes Value
2
EF Number No Value
1



Ss Description Yes Value
3
Ss Description No Value
0



EF Description Yes Value
2
EF Description No Value
1



Pr Number Yes Value
3
Pr Number No Value
0





Ss Number Yes Value
3
Ss Number No Value
0




Pr Description Yes Value
3
Pr Description No Value
0

Structural Foundation



EF Number Yes Value
0
EF Number No Value
0




Ss Description Yes Value
0
Ss Description No Value
0




EF Description Yes Value
0
EF Description No Value
0



Pr Number Yes Value
0
Pr Number No Value
0





Ss Number Yes Value
0
Ss Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Structural Framing




EF Number Yes Value
0
EF Number No Value
6




Ss Description Yes Value
2
Ss Description No Value
4




EF Description Yes Value
0
EF Description No Value
6



Pr Number Yes Value
2
Pr Number No Value
4




Ss Number Yes Value
2
Ss Number No Value
4




Pr Description Yes Value
2
Pr Description No Value
4


Structural Stiffener




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Structural Truss




EF Number Yes Value
0
EF Number No Value
0



EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0





Pr Number Yes Value
0
Pr Number No Value
0




Pr Description Yes Value
0
Pr Description No Value
0


Wall (Foundation)




EF Number Yes Value
0
EF Number No Value
0




EF Description Yes Value
0
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
0



Ss Description Yes Value
0
Ss Description No Value
0



Pr Number Yes Value
0
Pr Number No Value
0



Pr Description Yes Value
0
Pr Description No Value
0


Wall (Core-Shaft)




EF Number Yes Value
5
EF Number No Value
0




EF Description Yes Value
5
EF Description No Value
0




Ss Number Yes Value
0
Ss Number No Value
5



Ss Description Yes Value
0
Ss Description No Value
5



Pr Number Yes Value
4
Pr Number No Value
1



Pr Description Yes Value
4
Pr Description No Value
1

